


PIKE POLE



The head of a pike pole may turn after it has been forced through plaster ceilings/walls or any other type of construction. It may then become difficult to determine the direction in which the hook is pointing. This problem can be eliminated by filing small notches on the hook side of the handle.